BRAZOSPORT HIGH SCHOOL EXECUTIVE SUMMARY



	/ Assessment	1156				
Design Capacity: Functional Capacity:		1150				Percent Occupied: 96%
		983				rerective occupied. 50%
Current Enrollment		941				85% Capacity is assumed full
	Constructed : 1949/2005	5.1				
-	Current Square Footage : 48	34.765				
0	ent Grading	1-Pass			5- Fail	
			2 3	4		Note: Score over 3 recommend replacement
Site	Parking and Drives					Concrete entry drives & parking in good condition
	Sidewalks				N	Newer sidewalks in good condition. Older paving cracked & patched.
	Landscape/Irrigation					Animal landscaping. Mostly grass/clover & trees.
	Play Grounds					No playgrounds.
	ADA Accessibility					Accessible sidewalks/parking/entries
	Utilities& Drainage					Adequate drainage. Area drains.
	Site Lighting				Р	Pole lighting & wall packs.
	Security					Good. Security cameras around perimeter.
Exterior	Exterior Walls					Recent addition in good condition. Original has stained walls.
	Structure/Foundation					Good to fair building structure/foundations.
	Windows					Alum. Windows2005: double pane glass, 1949: single pane
	Doors/Entrances					Aluminum storefront doors in good condition at 2005 addition.
	Roofing					Good; general maintenance recommended
	Weather/Waterproofing				D	Describe overall conditions of weather/waterproofing
	Canopies					Avadek canopy at secondary entrance. Fair condition.
Interior	TEA Compliance					
	Educational Adequacy				E	ducation Adequacy is generally good.
	Finishes					inishes are in good condition.
	Restrooms				R	Restroom fixtures & finishes in good condition.
	Food Service				G	Generally in good condition with normal wear & functional.
	Doors/Hardware				G	Generally in good condition with some normal wear.
	Accessibility				P	Plumbing fixtures, hardware, and circulation are generally accessible
	ACM materials				N	No ACM materials
	Code requirements				С	Current year building code used
MEP	Mechanical					
	Units				G	Good-roof mounted eqp;recomm maintenance
	Ductwork			1	d	luctwork in excellent condition
	Exhaust				g	reat shape, ensure all are running and interlocked with AHU
	Electrical		·			
	Building service				P	Pad mounted XFMR / elevated
	Panels				E	xcellent
	Distribution				N	J/A
	Plumbing					
	Infrastructure				C	opper piping
	Fixtures				Y	/es. Good condition
	Life Safety Systems					
	Fire Sprinkler				G	Good. Corrosion-Recommend painting pipes
	Fire Alarm				Y	/es. Good condition
	Emergency Lighting				Y	′es, however burn 24/7
	Exit Signage				A	Appears to be adequate, interpretation by FM could require more
	Technology					
	Data				A	Adequate teacher/student computer drops.
	Wi Fi				A	Available

Total Score - 2.18

BRAZOSPORT HIGH SCHOOL EXECUTIVE SUMMARY



OVERALL SUMMARY & RECOMMENDATION

The main Brazosport HS building was completed in 2005 as in good condition. Educational adequacy, exterior & interior conditions, and interior function all are at acceptable levels. Older parts of the school such as the fieldhouse do require some maintenance, as finishes & exterior conditions, such as parking, are deteriorating.

The main Brazosport HS building is in good condition and only needs general ongoing maintenance. Recommended work would be making the fieldhouse accessible and upgrading the deteriorating parking lots/roadways near the field house and at Hopper field. Additional recommended work would include addressing the waterproofing at the auditorium.