Hopper Field District Stadium EXECUTIVE SUMMARY



Capacity Assessment								
Design Capacity:		1335				Percent Occupied: 0%		
<u> </u>		1176				Percent Occupied: 0%		
Functional Capacity: Current Enrollment		0				85% Capacity is assumed full		
Building Constructed : 1949/1961/2004								
Building Current Square Footage : 25,000 after '04 renovation								
Assessment Grading 1-Pass 5- Fail								
	Scale	: 1	2 3	4	5 Note: Score over 3 reco	ommend replacement		
Site	Parking and Drives				Fair to good condition,	most parking is across the street at high school		
	Sidewalks				Good condition overall			
	Landscape/Irrigation				Fair to good condition			
	Play Grounds				No playgrounds on site			
	ADA Accessibility				Tickets/concession boo	ths are not ADA compliant, all other areas are		
	Utilities& Drainage				Some conditions unkno	own, Normal wear in most areas good condition		
	Site Lighting					ng lot lighting or sidewalk lighting		
	Security					rimeter fencing and natural terrain as barriers		
Exterior	Exterior Walls				· · · · ·	Good condition, newer construction		
	Structure/Foundation				Some conditions unkno	own at this time		
	Windows				Good condition			
	Doors/Entrances	Fair to good condition						
	Roofing	Modified Bitumen roofs are in good condition						
	Weather/Waterproofing							
Canopies				_	,	Good condition, normal wear		
Interior	TEA Compliance			_	N/A			
	Educational Adequacy			-	N/A			
	Finishes Restrooms			-		Good condition, normal wear, minor maintenance issues Very good condition overall both public RR and locker rooms		
	Food Service			Some interior conditions unknown at this time				
	Doors/Hardware			-	All interior doors & hardware in good condition			
	Accessibility			-	All interior public spaces are ADA Compliant			
	ACCESSIBILITY ACM materials			ACM is not suspected in updated construction				
	Code requirements			-	· · ·	Building code used is unknown at this time		
MEP	Mechanical				Building code used is d			
	Units				Lckr Rm/PressBox-good	d/Ticket & Concess (locked)		
	Ductwork			+	Overall condition of du			
	Exhaust					ion, however off during review		
	Electrical							
	Building service				Fair condition			
	Panels			1	Good			
	Distribution				N/A			
	Plumbing							
	Infrastructure				Good Condition			
	Fixtures				ADA Compliant			
	Life Safety Systems							
	Fire Sprinkler				No sprinkler system vis			
	Fire Alarm			Present & good condition				
	Emergency Lighting			\perp	Not observed. No gene	rator		
	Exit Signage				Yes			
	Technology							
	Data			_	Adequate			
	Wi Fi				Available			

Total Score - 2.46



OVERALL SUMMARY & RECOMMENDATION

The BISD Stadium field is in good condition. There are some ADA compliance and finish issues with fixtures and restrooms in the ticket office and concessions.

RECOMMENDATIONS: For the BISD Stadium complex it is recommended to address some of the non compliant accessiblity issues and upgrade finishes for concessions and ticket office. We recommend scheduled and routine maintenance and upkeep to keep the facility in good condition.